



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 031/2020

DATE: 23rd January 2020

S. O. P: TFN

TEXT OF WARNING

Central Gulf: Bahrain – Under Water Dive Site

BA Charts: 3790, 2837, 2847, 2858

A Boeing 747 submerged in the northern waters of Bahrain as part of an underwater dive site in the following final position (WGS-84):

26-35.930N 050-58.479E

The Aircraft's tail is approximately 18.5m high when the Aircraft is lying flat on the seabed.

The temporary Emergency Wreck Buoy with top mark and AIS deployed on Lat. 26-35.941N, Long. 050-58.512E to mark the location of Bahrain Dive plane.

All vessels in the vicinity are requested to navigate with extreme caution and keep a 2 Nm Exclusion zone around this area.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END OF TEXT WARNING

Col: 031/2020, 23, 2020, 3790, 2837, 2847, 2858, 747, 84, 26, 35.930, 050, 58.479, 18.5, 26, 35.941, 050, 58.512, 2.

MENAS is an ISO 9001:2015 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org