



**MIDDLE EAST NAVIGATION AIDS SERVICE  
NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)**

**NAVIGATION WARNING TO ALL GULF SHIPPING**

**NAV NO:** 070/2016

**DATE:** 24<sup>th</sup> July 2016

**S. O. P:** TFN

*TEXT OF WARNING*

**Southern Gulf – South Cardinal Buoy Missing**

BA Charts 2837, 2887, 2888, 2441

A South Cardinal buoy at position Lat 26° 10.700N Long 055° 20.800E has been reported off station. The Buoy was reported on 220630 UTC JULY 16 at position Lat 26°06.770N Long 055°19.330E in TSS TUNB FARUR Channel.

Mariners are requested to exercise caution around the area.

**Issuer: MENAS Maritime Operations Centre, Bahrain  
Megulite**

*END TEXT OF WARNING*

Col: 070/2016, 24, 2016, 2837, 2887, 2888, 2441, 26, 10.700, 055, 20.800, 220630, 16, 26, 06.770, 055, 19.330

**MENAS is an ISO 9001:2008 Certified Service**

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: ++973 17828541 Fax: ++973 17727765 Email [info@menas.com.bh](mailto:info@menas.com.bh)

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at [menas.org](http://menas.org) Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through [menas.org](http://menas.org)

**[www.menas.org](http://www.menas.org)**