



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 354/2020

DATE: 12th December 2020

S. O. P: TFN.

TEXT OF WARNING

Southern Gulf: Temporary Shifting of Buoy Dalma-1

BA Chart: 3179, 2889

Dalma-1 Buoy has been temporarily shifted from the charted position to the new position 24-31.960N, 052-30.449E.

Mariners are requested to navigate with caution while transiting this area.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END OF TEXT WARNING

Col: 354/2020, 12, 2020, 1, 3179, 2889, 1, 24, 31.960, 052, 30.449

MENAS is an ISO 9001:2015 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email: info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org